

- OBTAIN CONTOURS AND DIM. FROM MASTER PATTERN P/N 41228-202-128-004 FABRICATE USING MOLD 41202-202-128-004.
- OBTAIN CONTOURS AND DIM. FROM MASTER PATTERN P/N 41228-202-128-003 FABRICATE USING MOLD 41202-202-128-003.
- OBTAIN CONTOURS AND DIM. FROM MASTER PATTERN P/N 41228-202-128-002 FABRICATE USING MOLD 41202-202-128-002.
- OBTAIN CONTOURS AND DIM. FROM MASTER PATTERN P/N 41228-202-128-001 FABRICATE USING MOLD 41202-202-128-001.
- A FABRICATE IN ACCORDANCE WITH ERA PROCESS SPECIFICATION No.

L				41228-202-128-004	R/	H LOWER	₹	<u>A</u>	-	·		
				41228-202-128-003	; L/	H LOWER	}	14				
				41228-202-128-002	! R/	H LOWER	₹	ΛA				
			41228-202-128-001 PART NO.		L/	H LOWER		1/2				
						NAME		STOCK SIZE		MATERIAL	MATL.SPEC	ZONE
	NO. REQ'D	PER	ASSY			LIST	OF MAT	ERIAL				
PRC	PRIETARY					UNLESS	DRFTSMN T.	HARVILLE	7/19/93	TITLE		
ロバロ	RIGHTS NOTICE THESE DATA ARE					OTHERWISE SPECIFIED	CHECK			EXTERNAL CONDUIT		IT
		1 1	i		- 1	1						
THI	ESE DATA ARE	-004	1 1	4000 004 007	+-	X.±.1	STRESS			LAILIN	WILL CONTDO	11
THI	ESE DATA ARE	-004 -003	1 4	-1228-201-003	<u> </u>	X.±.1 XX.±.03 XXX.±.010	STRESS PROJ. ENGR.			DWG. SIZE C	SCALE NON	
THI PRO ERA DISCLI DUCTI THESE PURPO DEN Y		-004 -003 -002 -001		-1228-201-003 -1228-201-003	-	XX.±.03	PROJ.			DWC 517E	SCALE NON	